



Plate 1: View from Church Road and Graig Road, at the base of Church Road drainage system



Plate 2: Close up of wall shown in Plate 1, note bricks being eroded by water and moss

PROJECT: PANTTEG LANDSLIDE

PLATES



EARTH SCIENCE PARTNERSHIP

33 Cardiff Road, Taffs Well, Cardiff CF15 7RB

Tel: 029 2081 3385 enquiries@earthsciencepartnership.com